


ODB: disp_BC_round3_v02.odb Abaqus/Standard 6.14-1 Tue Nov 14 15:47:13 Eastern Standard Time 2011

Step: Step-6
Increment 1: Step Time = 1.000



Material Library Module: Property Model: Model-1 Part: Part-3

Section Assignment Manager

Section Name (Type)	Material Name	Region
✓ Section-1-matrix (Solid, Homogeneous)	Matrix	Set-1
✓ Section-2-fiber (Solid, Homogeneous)	Carbon Fiber	Set-2

Create... Edit... Delete... Dismiss

Edit Section Assignment

Region: Set-1



Section: Section-1-matrix

Note: List contains only sections applicable to the selected regions.

Type: Solid, Homogeneous

Material: Matrix

OK Cancel



Material Library

(2)
ons
(2)
/
put Requests (1)
Output Requests (1)
nts
Active Mesh Constr
ns
in Properties
Controls
initializations
stabilizations
its
or Sections
les
id Fields
ng Rules
tion Tasks

Processes
ns
1 Processes

Section Assignment Manager

Section Name (Type)	Material Name	Region
✓ Section-1-matrix (Solid, Homogeneous)	Matrix	Set-1
✓ Section-2-fiber (Solid, Homogeneous)	Carbon Fiber	Set-2

Edit Section Assignment

Region
Region: Set-2



Section
Section: Section-2-fiber



Note: List contains only sections applicable to the selected regions.

Type: Solid, Homogeneous
Material: Carbon Fiber

OK Cancel

Create... Edit... Delete... Dismiss





ODB: disp_BC_round4_v01.odb Abaqus/Standard/s11.rvt Wed Nov 17 10:42:01 Eastern Standard Time 2017



Step: Step-1
 Increment 1: Step Time = 1.000
 Primary Var: S, S11
 Deformed Var: U Deformation Scale Factor: +2.000e-01